

Customer reference number*

DMR1000

Teasing SO number*

T-SO1234567

Teasing article number*

47300211

Serial number / Lot number / batch number

LN: 58901111

Amount complaint (pcs/meters)*

6pcs

Company name*

Testing B.V.

Customer contact*

Alex

Customer contact email adress*

alex@testing.com

Customer contact telephone no.*

+886 03 1234567

Please include the country code in your phone number.

Creation date*

January 31, 2023

Problem description

Medium

Nitrogen

Pressure (Bar(g) / Bar(a) or MPa)

5.6 Bar(g)

Pressure (Constant or pulsating)

Please choose an option

Temperature (°C)

25degreeC

Environment

Please describe the environment in which the problem occurred.
Such as inside/outside building.

Room Temperature, within cleanroom

Clear description of complaint.*

What is the object and what is the deviation?

Leaking was found during pressure testing with a bubble test. //

Remarks

You could add extra information to clarify the complaints.

Testing method: 5.6 bar for 10mins
Visual check if any leaking or not
This is 3rd time we found same type of fitting leaking.

Please add photos if possible to clarify the complaint.

Photos_1.jpg

For example: .gif, .jpg, .png, .pdf, .zip, .stp, .xlsx, .csv, .xls, .doc